# 10 year guarantee

for use of MACO RUSTICO shutter hardware with

**PREMIUM-PLUS** surface finish

Mayer & Co Beschläge GmbH, 5020 Salzburg, Alpenstraße 173, Austria, grants a SURFACE FINISH GUARANTEE of 10 years, in excess of the legal period, for the use of MACO PREMIUM-PLUS hardware, commencing on the date for delivery of the hardware to the fabricator.

(delivery date from January 2013)

#### **GUARANTEE CONDITIONS**

The guarantee applies only to fabricators of MACO hardware.

#### **GUARANTEE CLAIM**

 Clearly visible impairment of the surface (visible surface in mounted condition) due to ferric oxide or loosening of the surface through corrosion of the base material.

## **GUARANTEE SERVICES**

- Replacement of the defective component or supply of a component with equivalent functionality free of charge
- Further reimbursements are excluded by MACO.

Preconditions for guarantee detailed on the back



## 10 year guarantee

for use of MACO RUSTICO shutter hardware with

**PREMIUM-PLUS** surface finish

### PRECONDITIONS FOR GUARANTEE

- Compliance with all MACO specifications and processing instructions
- Use of MACO RUSTICO stainless steel hardware screws
- Verifiable compliance with all obligations to provide instructions to the end user
- Intendend use in accordance with the product-specific MACO catalogues
- Verifiable maintenance (through fabricator's service or guarantee certificate) in accordance with MACO operating and maintenance instructions
- Return of the defective parts together with the original invoice

## **GUARANTEE EXCLUSION**

- Marked items in the MACO RUSTICO catalogue
- Improper storage or transport
- Mechanical damage of the surface finish
- Exposed metal at cuts and thereof resulting corrosion
- Setting ranges, clamping screws, adjusting screws, and moving parts
- Components which cannot be coated with PREMIUM-PLUS for manufacturing reasons
- Unsuitable or unintended use
- Transfer of corrosion through foreign materials
- Use of aggressive or abrasive cleaning agents
- Natural wear, soiling or salt deposits
- Modifications or self-repair
- Deposition of loose rust on undamaged surfaces

MAYER & CO BESCHLÄGE GMBH Alpenstraße 173

Alpenstraße 173 A-5020 Salzburg

+43 662 6196-0 maco@maco.eu www.maco.eu Order No. 758518EN – Creation date: January 2014
Date of update: 2<sup>nd</sup> June 2017
All rights reserved and subject to change.

